



(A) TYPICAL CRIPPLE WALL BRACING DETAIL

NOTES:

1. THIS DETAIL SHOWS A SAMPLE CRIPPLE WALL WHICH HAS UNDERGONE A TYPICAL SEISMIC STRENGTHENING.
2. THIS DETAIL IS NOT INTENDED TO SUPERSEDE REQUIREMENTS CONTAINED IN THE SPECIFIC INSTALLATION DETAILS ON SHEET 2 OR THE PLAN SET BOOKLET.